



Rev. 3 Changes made to harness are on the AC adapter harness being changed to a sealed Deutsch DT6-43 9/29/08  
 Rev. 4 Changes made to harness are the cable used model wiring length of wires & Viper motor drive added 9/29/08  
 Also wiring changes for the parking brake switch inside the tunnel  
 Rev. 5 Changes Change to larger IC heater connector. Changes for brake light switch, add anti-drive relay with ICE charger  
 Rev. 2 Changes Integration of most sub harnesses U3717A, U2569A, U2567A & U2566A, Removal of speeds capacitor, Addition of viper motor wiring